


# AIRCRAFT MOUNT IMPROVED

The M240H machine gun has replaced the M60D on all Army aircraft. To make the M240H easier to use, the Army is improving the UH-60 and CH-47 gun mounts. These improvements include:

- clevis pins, washers and cotter pins replacing the E clips
  - roller-bearing style cam follower assembly replacing the three cam followers on the CH-47
  - new quick-release pin and lanyard for the UH-60 travel lock
  - more durable brass-and-links catch bag and a shorter, more durable collector assembly
- The catch bags and collector assemblies will be issued as no-cost replacements during FY 09.


HERE ARE THE NEW ASSEMBLY NSNs AND THEIR PART NSNs...




## UH-60/CH-47 M240H Solid Mount Assembly

- |                                |   |
|--------------------------------|---|
| LH UH-60, NSN 1005-01-526-5134 | CH-47 ramp, NSN 1005-01-526-5139        |
| RH UH-60, NSN 1005-01-526-5135 | CH-47 right door, NSN 1005-01-526-5136  |
|                                | CH-47 left window, NSN 1005-01-526-5137 |


## M240 Solid Mount Assembly Parts



## CH-47 M240H Machine Gun Rear Ramp Mount Assembly



## M240H Solid Mount Assembly Pintles and Associated Equipment



For more maintenance info on the mount, see TM 9-1005-262-13 (up to Ch 5).  
For more info on repair parts, see TM 9-1005-262-23p (up to Ch 3).