

M88A1  
Recovery  
Vehicle...

# EXHAUSTING SEARCH FOR NEW PIPE

I NEED TO GET YOU A NEW EXHAUST PIPE BUT THESE TMS TELL ME TO ORDER TWO DIFFERENT PIPES.

WHICH ONE IS THE RIGHT ONE?

I DON'T KNOW, BUT I BET HALF-MAST DOES!



Dear Half-Mast,


We're working on an M88A1 and need to order a new exhaust pipe for the exhaust manifold. Unfortunately, there's a disconnect between the vehicle and engine parts manuals.

According to Item 9 in Fig 13 of TM 9-2350-256-24P-1 (May 92), we're supposed to order NSN 2990-01-017-5187. But Item 16 in Fig 24 of TM 9-2815-220-24P (Dec 05) says to order NSN 2990-01-085-3831. Which one is correct?

SPC D.J.S.

THE ENGINE PARTS MANUAL, TM 9-2815-220-24P, IS CORRECT. USE NSN 2990-01-085-3831 TO GET THE EXHAUST PIPE YOU NEED.

IT TURNS OUT THE WRONG PART NUMBERS WERE LISTED FOR FOUR OF THE ITEMS IN FIGURES 13 AND 14 OF TM 9-2350-256-24P-1, INCLUDING THE ONE FOR THAT EXHAUST PIPE. JOT DOWN THESE CHANGES UNTIL THE TM CAN BE UPDATED...



Item/Fig	Correct PN	Correct NSN 2990-01-
Item 7, Fig 13	11684193	017-5186
Item 9, Fig 13	11684185-1	085-3831
Item 4, Fig 14	11684194	017-5187
Item 11, Fig 14	11684187-1	085-3832

PS 682