


A LITTLE FUSE NEWS

THESE FUSES MAY BE SMALL, BUT THEY HAVE A BIG IMPACT!



Dear Editor,

I'm the AN/TSC-156B Tac Sat Phoenix system ILS manager and I need to alert the field of some NSN changes for fuses. Six of the NSNs for fuses listed in TM 11-5895-1830-13&P have been canceled and the FED LOG doesn't reference replacement NSNs.

Here are the canceled NSNs, the NSNs that replaced them, and where they're located in the TM:

Old NSN 5920-01-	New NSN 5920-	Item	Fig/Table
520-9140	01-122-4181	2 2 19	Fig C-27 Fig C-28 Table D-13
323-7953	01-120-3823	7	Fig C-20
522-0272	00-407-0310	4 26	Fig C-20 Table D-13
513-3669	01-386-8116	8 16	Fig C-53 Table D-13
520-9148	00-280-5066	10 13	Fig C-34 Table D-13
522-3308	01-378-3869	2 17	Fig C-5 Table D-13

Examples of areas in TM 11-5895-1830-13&P to be changed:

Fig C-27

Item No.	SMR Code	NSN	CAGE Code	Part Number	Description and Usable on Code (UOC)	Qty
2	PAOZZ	5920-01-520-9140	75915	21801.6	Fuse, cartridge 7182953-10	2

Fig C-20


Item No.	SMR Code	NSN	CAGE Code	Part Number	Description and Usable on Code (UOC)	Qty
7	PAOZZ		75915	218025	Fuse, cartridge 7182953-12 (For 4008975+000 only)	2

Table D-13

Item No.	Description	NSN	CAGE Code	Part Number	UI EA	Qty
13	Fuse, cartridge	5920-01-520-9148	06401	7186732-05	EA	2
16	Fuse, cartridge	5920-01-513-3669	06401	7182953-23	EA	4
17	Fuse, cartridge	5920-01-522-3308	06401	7193225-00	EA	2

I also want to point out that the notebook computer battery NSN, NSN 6140-01-518-4975, has been changed to NSN 6140-01-539-0599. That battery is Item 5 in Fig C-29, Item 5 in Table D-11, and Item 28 in Table D-13.

Donna G. Zeimer
ILS Manager, PM-WIN-T



NEW FUSES REPORTING FOR DUTY!

Editor's note: Thanks, Donna, for the updated info. Nothing is more frustrating than to find an NSN is no longer good and the replacement is not listed on the FED LOG or AMDF. One more thing, Phoenix users, about TM 11-5895-1830-13&P. The numbering system identifying the figure in the Comprehensive NSN List seems to be off by one number in many cases. That's the case with five of the six fuse NSNs. It doesn't change anything, but might confuse your search efforts.