



NOT SURE IF THE SOFTWARE IN YOUR MISSION PROCESSOR UNIT (MPU) OR TARGETING STATION CONTROL PANEL (TSCP) IS UP-TO-DATE?

Software Updates a BREEZE on AKO



NO WORRIES. THERE'S NOW A ONE-STOP AKO WEBSITE THAT LISTS THE MOST CURRENT SOFTWARE VERSIONS.

AND, IF YOUR SOFTWARE HAPPENS TO BE OUT-OF-DATE, YOU CAN DOWNLOAD AND BURN THE NEW MISSION LOADER/VERIFIER (MLV) SOFTWARE FILES TO A CD FOR INSTALLATION ON YOUR MPU AND TSCP.



JUST GO TO:
<https://www.us.army.mil/suite/page/453627>

IF YOU CAN'T BURN CDS, YOU CAN GET THE SOFTWARE UPDATES BY CALLING DRS SUSTAINMENT SYSTEMS, INC.'S (DRS-SSI) BRAD NAUMER AT (314) 553-4082, OR BY EMAIL:
bnaumer@drs-ssi.com

QUESTIONS? CONTACT TACOM-ROCK ISLAND'S ANDREW MCCALLEY, DSN 793-3976, (309)-782-3976, OR BY EMAIL:
andrew.mccalley@us.army.mil