


# Large Demand, Small Supply on Antenna



Dear Editor,

I need your help in getting the word out about the supply of AS-3711 antenna assemblies, NSN 5985-01-179-5150, used with the ALQ-136(V)5 countermeasures set (CMS). The word is, the supply is low and won't be replenished until the Spring of 2011.

In the meantime, it is essential that serviceable antenna assemblies not being used and unserviceable antenna assemblies that are warehoused be turned in.

Send these valuable antennas to:  
Commander DDDTP  
W25G1W  
11 Hap Arnold Blvd.  
Bldg. 2, Bay 1  
Condition Code \_\_\_\_\_

Tobyhanna, PA 18466-5027  
Include the condition code that you have assigned it. Your unit will get a serviceable credit or an unserviceable credit in exchange.

Joseph F. Della Vecchia  
ASE Inventory Manager  
Ft Monmouth, NJ

**Editor's note:** Okay, troops, it's time to soldier up and get those antennas turned in for repair and reissue. You might not be hurting, but down-the-road, without your help, a future member of your unit could be. If you have questions, contact Mr. Della Vecchia by calling DSN 992-7850 or (732) 532-7850 or email him: [joseph.dellavecchia@us.army.mil](mailto:joseph.dellavecchia@us.army.mil) Or, contact Gerald Conrad at DSN 795-6644 or (570) 615-6644. His email address is: [gerald.allen.conrad@us.army.mil](mailto:gerald.allen.conrad@us.army.mil)