



**I**f you haven't turned in your old AN/ASM-146A, B or C shelter-mounted electronics maintenance shop for the major MWO that upgrades it to a D, E, or F model, what are you waiting for?

A good excuse?

If so, now you've got one!

The 15-ft pigtail power stub cable, NSN 5955-01-149-6875, Item 97 of Fig 1 of TM 11-4940-238-24P-1, used with the old shelter models has a connector that is not watertight. Under wet conditions, that cable can shock you and damage the shelter. For more info on this hazard, go to your CECOM LAR and ask for a copy of Technical Ground Precautionary Action Message 2010-004.

Better, yet, why not take the opportunity this faulty cable has given you and turn in your shelter to the Reset program at Tobyhanna Army Depot. Tobyhanna will do the Reset and apply the MWO for free! Think of it like turning in a Pinto and getting a Mustang and not paying one red cent!

Learn more about the Reset program and the MWO by contacting Kenneth Shedlock at DSN 992-5549 or (732) 532-5549. You can also email him:

[kenneth.shedlock@us.army.mil](mailto:kenneth.shedlock@us.army.mil)

Or, contact Steve Rowe at DSN 992-4635 or (732) 532-4635. His email address is:

[steven.t.rowe1@us.army.mil](mailto:steven.t.rowe1@us.army.mil)