

M872A4 Semitrailer Landing Leg NSN

If you order the M872A4 landing leg supports, NSN 2590-01-522-6745 and NSN 2590-01-522-6749, shown as Item 1 in Fig 27 of TM 9-2330-331-14&P (Dec 05), you'll get the wrong parts. Get the correct landing legs with NSN 2590-01-176-4787. That assembly brings both legs.

WINTER READING

If you're heading to mountains or snowfields this winter, take along these field manuals:

- FM 3-97.6, *Mountain Operations*
- FM 3-97.61, *Military Mountaineering*
- FM 31-70, *Basic Cold Weather Manual*
- FM 31-71, *Northern Operations*

They're essential reading for Soldiers deployed in high country or in freezing climates. The FMs cover tactics, operations, survival skills, clothing, shelter, personal gear, sleds, first aid and much more. You'll find the FMs at the Army Publishing Directorate website:

<http://www.apd.army.mil>

780T Paving Machine Parts

Repair parts for paving machines are getting hard to find. Without NSNs, these parts aren't always available by the CAGE and PN called out in TM 5-3895-373-24P, either. For help finding parts, contact TACOM's paving machine team at DSN 273-3114/3115/3116, Comm (586) 239-3114/3115/3116, or email:

DAMI_rollers@conus.army.mil

M1070 HET CONVERSION KIT

Use conversion kit, NSN 2815-01-456-1281, to upgrade the M1070 HET tractor's DDEC II engine to the DDEC III/IV. You'll find the installation instructions on Pages 18-3 and -4 of TM 9-2320-360-34-1. Also, you need to install cab conversion kit, NSN 2510-01-456-2278, when you upgrade to the DDEC III/IV engine.

MW24C Defogger Fan

Use NSN 4140-01-267-1844 to get the scoop loader's defogger fan. This NSN replaces the parts info shown as Item 15 in Fig 119 of TM 5-3805-262-24P.

M1117 ASV Fuel Transmitters

Get the fuel transmitter (commander's side) for the armored security vehicle using NSN 6680-01-554-1196. Use NSN 6680-01-554-1208 to get the transmitter that's on the driver's side. Make a note until these NSNs show up for Items 1 and 2 in Fig 29 of TM 9-2320-307-24P.

M113A2 FOV Fuel Cap

Get a new fuel cap for your M113A2 FOV using NSN 5342-01-467-5645. Both NSN 5340-01-083-5674 and NSN 5342-01-387-4007, which are shown as Item 9 in Fig 23 of TM 9-2350-261-24P (Aug 05), are terminal items.

M1009 CUCV BRAKE PADS

To get the front brake pads for the M1009 CUCV truck, use NSN 2530-01-158-1458, PN 12321426. This NSN replaces the parts info shown for Item 13 in Fig 88 of TM 9-2320-289-20P.

Up-armored HMMWV Filter

To get an air dryer filter for the air conditioning system on up-armored HMMWVs, use NSN 4130-01-548-1188. This NSN replaces the parts info shown as Item 5 in Fig 274A of TM 9-2320-387-24P w/CH 2.

HEMTT A4 Wrecker BII Crowbar Update

The HEMTT A4's IETM, TM 9-2320-326-14&P, EM 0288, has an error in the BII for the A4 Wrecker. The crowbar, NSN 5120-00-224-1390, shown as Item 29, doesn't belong on the front passenger side fender. It goes under the cargo body, above the fuel tank. Make a note until the IETM is updated so you can store it in the right place.

LED Flashlight

Need a flashlight to light up those dark areas when pulling vehicle maintenance? Try using a 4-LED flashlight, NSN 6230-01-522-2506. The LEDs will last 10,000 hours or more. The flashlight takes 2 AA batteries and comes with a bungee-style wrist lanyard.

Bradley Fuel Cap NSN

To order a new fuel cap for your Bradley, use NSN 2590-01-482-1662. It replaces NSN 5342-01-418-8526, which is shown as Item 85 in Fig 154 of TM 9-2350-252-24P-1 (Mar 97 w/Ch 1, Feb 98) and Item 67 in Fig 135 of TM 9-2350-284-24P-1 (Aug 07). The old NSN is a terminal item.

MBU Tool Kit

The new MBU tool kit, NSN 5180-01-565-2047, has all the tools you need to repair and maintain your modern burner unit-V3 (MBU-V3). Each tool is industrial quality and comes with a warranty. There is one of each tool in the kit.

M997/A1 HMMWV A/C Compressor Belt

If MWO 9-2320-280-35-5 has been applied to your M997 or M997A1 HMMWV, you need a longer V-belt on your air conditioner compressor. The MWO tells you to use V-belt, NSN 3030-01-504-6408, but that's wrong. Make a note to use NSN 3030-01-084-4564 instead.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?