


Gen III Transmission "Turn In"

TURN IN
UNSERVICEABLE
TRANSMISSIONS!



WITHOUT
TURN-INS,
THERE ARE NO
TRANSMISSIONS
TO REPAIR!

The FMTV's hydraulic Gen III transmission, NSN 2520-01-493-6059, is no longer available in the Army's supply system. The transmission is ARIL coded "C" and needs to be turned in when it becomes an unserviceable asset.

Any of these transmissions that get cast aside in the motor pool rather than turned in puts a stress on the Army's supply system. Without turn-ins, transmissions aren't on hand for repair. That means transmissions are not ready for issue and your vehicle stays NMC!



SO, PACKAGE ANY
UNSERVICEABLE
TRANSMISSIONS
AND RETURN THEM
FOR REPAIR AT THE
NATIONAL MAINTENANCE
LEVEL AT FT BRAGG.

IT'S THE *BEST*
WAY TO MAKE
SURE THERE'S A
REPLACEMENT
TRANSMISSION
WHEN YOU NEED
ONE.

CONTACT
YOUR
LOCAL
TACOM
LAR IF
YOU NEED
HELP.