

M1-Series  
Tanks...

# No Pain, No Gain?



The gun mount exerciser (GME), NSN 4933-01-346-1791, was designed to exercise both 105mm and 120mm guns. So it can be a little confusing as to which way to position the GME when exercising the gun.

Get it wrong and the gun won't get the exercise it needs. Plus, the GME won't hold properly and you might damage the clamp.

To mount the GME properly, make sure the 120mm arrow is pointing **at the bore evacuator**. Then, exercise away!

