

## M25 BINOCULARS GO TO DEPOT, NOT DLA DISPOSITION SERVICES

When the M25 stabilized binoculars, NSN 1240-01-410-7418, break, some units are sending them to DLA Disposition Services (formerly DRMO). That's **wrong**. The M24 has an SMR code of PAODD, which means it's repaired or disposed of at depot. Turn in broken M25s so they can be shipped to depot for repair.

## TOOLBOX BRIMS WITH HANDY INFO

The Range & Weapons Safety Toolbox at the US Army Combat Readiness/Safety Center is a one-stop shop for many resources on range operations and safe weapons handling. The toolbox also links to recently updated range and safety publications, so the most current info is at your fingertips. Visit:

<https://safety.army.mil/rangeweaponssafety/>

For help, call DSN 558-1390, (334) 255-1390, or email: [usarmy.rucker.hqda-secarmy.mbx.safe-helpdesk@mail.mil](mailto:usarmy.rucker.hqda-secarmy.mbx.safe-helpdesk@mail.mil)

## GRAT Adds New Features

The Ground Risk Assessment Tool (GRAT) at the US Army Combat Readiness/Safety Center (USACR/Safety Center) helps you identify hazards and controls for missions or activities. GRAT's recent upgrades include electronic signatures and a draft-saving feature so you can back up your work while completing the worksheet. To access GRAT, visit:

<https://grat.safety.army.mil/GRAT/>

For help, call DSN 558-1390, (334) 255-1390, or email: [usarmy.rucker.hqda-secarmy.mbx.safe-helpdesk@mail.mil](mailto:usarmy.rucker.hqda-secarmy.mbx.safe-helpdesk@mail.mil)

## M1-Series Tank Fuel Pump Sealing Compound

Mechanics, get a 50ml tube of sealing compound (commonly referred to as "grape jelly") for installing the in-tank electrical fuel pump gaskets by ordering NSN 5330-01-325-6993. NSN 8030-01-262-3560, which is listed as Item 119 in Appendix C of TM 9-2350-264-20-1-5 (Mar 03, w/Ch 5, Jun 09) and Item 139 in WP 1434 of TM 9-2350-388-23-1-7 (Feb 09), has been removed from the supply system.

## LRT-110 Crane Wire Rope

Get a replacement wire rope (cable) for your LRT-110 7 1/2-ton crane's winch with NSN 4010-00-171-6315 (PN 8694151, CAGE 19207). PN 1269-180, which is listed as Item 3 in Fig 13-1 of TM 5-3810-305-24P (Jul 91), does not cross to an NSN. When you receive the new wire rope, cut it to a length of 180 feet to fit the winch.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life *right now* on the Condition of Your Equipment?