

# ALL THREE PARTS TO DEPOT



IF YOU MAINTAIN THE LONG-RANGE ADVANCED SCOUT SURVEILLANCE SYSTEM (LRAS3) INFRARED NIGHT VISION SIGHT (AN/TAS-8), LISTEN CAREFULLY!

WHEN YOU SEND THE LRAS3'S LASER RANGE FINDER, NSN 1240-01-486-5003, TO THE DEPOT FOR REPAIR, REMEMBER THIS: SEND THE ENTIRE LASER RANGE FINDER.

THE LASER RANGE FINDER IS MADE UP OF THREE PARTS...



- transceiver (laser)
- power supply circuit card
- range logic circuit card

SOME UNITS ARE SENDING ONLY ONE OR TWO PARTS TO THE DEPOT.



OK, NOW WHERE'S THE TRANSCIEVER?

**WITHOUT ALL THREE PARTS, THE DEPOT CAN'T MAKE THE LASER RANGE FINDER WORK!**

AND THE SUPPLY SYSTEM WON'T HAVE ENOUGH WORKING LASER RANGE FINDERS TO REPLACE THOSE THAT ARE DAMAGED!



SO PLEASE SEND THE DEPOT ALL THREE PARTS OF THE LASER RANGE FINDER FROM THE LRAS3.



FOR MORE INFORMATION, CONTACT CECOM LCMC ILS MANAGER LISA KEEFER, DSN 848-2929, (443) 861-2929, OR EMAIL: [lisa.e.keefer.civ@mail.mil](mailto:lisa.e.keefer.civ@mail.mil)