

# Good PM Needs Your Best Efforts!

FOR GOOD PM, YOU HAVE TO FOLLOW THE PMCS IN YOUR -10 TM...

...AND THEN YOU HAVE TO DO THE REQUIRED MAINTENANCE!



LATER ON...

THAT'S WHAT HAPPENS WHEN YOU DON'T FOLLOW THE PMCS CHART...

...AND YOU DON'T MAKE THE NEEDED REPAIRS!

