

Up-armored HMMWVs...

# B-KIT AND FRAG 5 KIT GLASS

GEE,  
MISTER!  
I'M REAL  
SORRY!

'S ALL RIGHT, KID. JUST  
WISH I HAD AN NSN FOR  
REPLACEMENT GLASS!



Dear Half-Mast,

My unit has some up-armored HMMWVs with the B-kit and others with the Frag 5 kit. Which NSNs should we use to replace the glass in the doors and window assemblies?

SFC I.C.

Dear Sergeant I.C.,

We have a clear answer for you. For M1151A1, M1152A1, M1165A1, and M1167 up-armored HMMWVs with the B-kit, the front and rear door glass comes with NSN 2510-01-581-2107; the left-door window assembly comes with NSN 2510-01-581-4181; and the right-door window assembly comes with NSN 2510-01-581-4183.

For M1151A1, M1152A1, M1165A1, and M1167 up-armored HMMWVs with the Frag 5 kit, the door glass comes with NSN 2510-01-563-8322; the left-door window assembly comes with NSN 2510-01-545-5898; and the right-door window assembly comes with NSN 2510-01-545-5899.

Finally, for M1114s with the Frag 5 kit, the door window assembly comes with NSN 2510-01-545-5856.

Half-Mast