



### MUST-USE EMAIL FOR PS MAGAZINE!

Heads up! PS no longer gets email sent to our old CONUS email ([logsa.psmag@conus.army.mil](mailto:logsa.psmag@conus.army.mil)). For a while, it was forwarded to our new Enterprise email (EE) account. No more. If you send email to our old CONUS account, it will bounce back to you. We know old habits die hard, but from now on use either our AKO email or EE address to reach us. Email PS at:

[half.mast@us.army.mil](mailto:half.mast@us.army.mil) or  
[usarmy.redstone.logsa.mbx.psmag@mail.mil](mailto:usarmy.redstone.logsa.mbx.psmag@mail.mil)

### LOGSA Updates Readiness Mailboxes

The Logistics Support Activity (LOGSA) has two new email addresses for readiness-related questions. For help with ground issues, email: [usarmy.redstone.logsa.mbx.readiness@mail.mil](mailto:usarmy.redstone.logsa.mbx.readiness@mail.mil)  
For aviation readiness assistance, email: [usarmy.redstone.logsa.mbx.airdata@mail.mil](mailto:usarmy.redstone.logsa.mbx.airdata@mail.mil)

### HMMWV Windshield Story Corrections

There were a few misprints in our HMMWV windshield story on Page 17 of PS 722 (Jan 13). SGT Adrian Isquierdo of the TXARNG noticed that we listed the wrong NSNs for the M1152A1's right-hand windshield and right-hand heated windshield. Get the right-hand windshield with NSN 2510-01-535-6000 and the right-hand heated windshield with NSN 2510-01-561-2540. And where you see M115A1 under HMMWV model, it should be M1151A1.

### EMS NG Help Desk Info

If you need help with the Electronic Maintenance System—Next Generation (EMS NG), the EMS Program Office invites you to use an online program called "Service Now" to open, view and track EMS NG incidents. Visit:

<https://oneil.service-now.com/ems/main.do>  
You can also call the EMS NG help desk at 1-877-445-1780 or email:

[Support@EMS-HelpDesk.com](mailto:Support@EMS-HelpDesk.com)

The help desk is staffed Monday to Friday from 7:30 a.m. to 4 p.m. EST.

### Download EMS NG Viewer and ADM

The Electronic Maintenance System—Next Generation (EMS NG) Viewer and Autonomous Diagnostic Manager (ADM) software are no longer distributed with interactive electronic technical manuals (IETMs). Download the most current versions of the EMS NG Viewer and ADM at: <https://www.us.army.mil/suite/files/26121198>

If you are unable to download the Viewer and/or ADM from AKO, email the EMS team at: [tacom-lcmc.ilsc\\_electronicmaintenancesystem@mail.mil](mailto:tacom-lcmc.ilsc_electronicmaintenancesystem@mail.mil)

Units can also request a copy of the Viewer and ADM software on DVD by writing:

Commander, US Army TACOM  
AMSTA-LCL-MP  
6501 E. 11 Mile Rd.  
Warren, MI 48397-5000

Please include your mailing address when you email or write.

### ARMY FORUMS MOVE: BRACE FOR BAD LINKS

We told you in PS 722 that the Army Professional Forums were moving to milSuite. One downside is that many of the old forum's links or downloads will no longer work. Some URLs we gave in the past or even a few future articles may have bad links. If you hit a dead URL, let us know and we will try to track down a new one or find another source for the information. Email:

[half.mast@us.army.mil](mailto:half.mast@us.army.mil) or  
[usarmy.redstone.logsa.mbx.psmag@mail.mil](mailto:usarmy.redstone.logsa.mbx.psmag@mail.mil)

### SUBMIT TACOM-RELATED PQDRS USING NEW ENTERPRISE EMAIL

The process for working TACOM-related product quality deficiency reports (PQDRs) hasn't changed, but the email address for submitting them has. So make a note that PQDRs must now be submitted through a new enterprise email address:

[usarmy.detroit.rdecom.mbx.tardec-product-qual-deficiency@mail.mil](mailto:usarmy.detroit.rdecom.mbx.tardec-product-qual-deficiency@mail.mil)

The old AKO address no longer forwards emails.

### Revised TM for Simple Key Loader

TM 11-5810-410-13&P, *Operators and Field Maintenance Manual Including Repair Parts and Special Tools List for Transfer Unit, Cryptographic Key AN/PYQ-10(C) Simple Key Loader (SKL)* has been revised. The revision features SKL user application software (UAS) versions 7.0 and 7.2. The 7.0 and 7.2 software include new menu options, detail buttons, procedures and figures. You'll find the TM on the LOGSA ETM website:

<https://www.logsa.army.mil/etms/online.cfm>

### NSN for M66 Cover

Need a canvas cover for the M66 ring mount? Order one with NSN 1005-00-707-0725. It costs around \$275. You can also now order a plastic "shower cap" cover with NSN 1005-01-610-9108 for around \$300.

### ARMY SAFETY PUB HITS STREETS

A new publication, DA Pam 385-26, *The Army Electrical Safety Program*, went into effect 1 February 2013. It offers guidelines for protecting Army personnel, facilities and equipment from electrical hazards. Download the publication at:

[http://www.apd.army.mil/pdf/files/p385\\_26.pdf](http://www.apd.army.mil/pdf/files/p385_26.pdf)

For more safety-related information, visit the US Army Combat Readiness/Safety website at:

<https://safety.army.mil/>

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life <sup>right now</sup> on the Condition of Your Equipment?