

M1074A1/M1075A1 PLS Steering Gear

Get the rear steering gear for your M1074A1/M1075A1 PLS tractor truck with NSN 3010-01-581-5058. It replaces NSN 2530-01-569-9930, which is shown as Item 1 in Fig 505 of TM 9-2320-319-13&P (EM 0298).

CONTAINERIZED KITCHEN WINCH

Need a good NSN for the winch that lowers and raises the side panels on your containerized kitchen? Item 1 in Fig 2 of TM 10-7360-226-13&P (Aug 01, w/Ch 4, Mar 07) lists the *wrong* NSN: 3950-01-515-2999. The correct NSN is 3950-01-511-1191. This NSN brings a winch repair kit that contains two winches. Make a note in the repair parts list until the TM is updated.

M1073 Trailer Wheel Assembly

Get a new wheel assembly for your M1073 7 1/2-ton flatbed trailer with NSN 2530-01-618-7916. Just the wheel comes with NSN 2530-01-305-9979. To get just the 11R x 17.5 tubeless radial "G" load range tire, order NSN 2610-01-603-8017. It's an approved substitute for the old "H" load range tire, NSN 2610-01-256-0080, which is no longer available.

Beware of Counterfeit CR123A Batteries

Counterfeit CR123A batteries are being sold to the public from a variety of sources. They look similar in size, shape and color to name-brand batteries such as Duracell, Energizer, Rayovac and others. These knock-offs may even have labels and logos similar to those on name-brand batteries. But make no mistake. The counterfeit CR123As are substandard. They can overheat and catch fire or explode when used, transported or stored. So, steer clear of counterfeit CR123As. Order authentic CR123As, NSN 6135-01-351-1131, only through the Army supply system. That way you can be sure you're getting good batteries.

CK Chassis Crank Handle

Currently, there's no NSN for the crank handle on the containerized kitchen's (CK) chassis, XCK2000. But you can order the crank handle on a DD Form 1348-6 using PN 1103-1945-01 and CAGE 2W888.

M26 Shotgun Buttstock NSN

Need a buttstock for the Army's new M26 shotgun? You won't find it listed in WP 0017-23 in TM 9-1005-341-23&P. Order the buttstock with NSN 1005-01-617-9519. The NSN will be added in the next revision to the TM.

The Solution for HEMTT Purging

Get a 5-gal container of cleaning compound (purging solution) for the M978 HEMTT fuel tanker with NSN 7930-01-350-7034. For a 55-gal container, use NSN 7930-01-350-7035. Make sure all purging solution is removed from the tanker before deploying, shipping overseas or sending to RESET. Follow the instructions in TACOM's ground precautionary message #94-02. You can view it at: https://tulsa.tacom.army.mil/safety/gpm/tacom_wn/gpm94-02.html

M777A2 Fire Control Telescope Mount

Page 7 of PS 722 (Jan 13) told you to prevent damage when towing the M119A2 howitzer by removing the M137A2 panoramic telescope from the M187A1 mount, as well as installing a plastic cover when the telescope isn't mounted. That info also applies to the M777A2 towed howitzer and its M171A1 mount. The original article can be viewed at:

<https://www.logsa.army.mil/psmag/archives/PS2013/722/722-07.pdf>

M149-SERIES TRAILER WHEEL BEARING ASSEMBLY NSN

Get a complete wheel bearing assembly for your M149-series water trailer with NSN 3110-00-100-5951. It replaces NSN 3110-00-100-3095, which is shown as Item 16 in Fig 17 of TM 9-2330-267-14&P (Jul 91). That NSN brings only the tapered roller section of the bearing.

SPECIALIST... GOT ANYTHING MORE TO SAY TO OUR READERS BEFORE LEAVING THIS EARTHLY REALM?

SURE DO, CONNIE. TELL THEM TO TAKE ADVANTAGE OF ALL THE SAFETY AND MAINTENANCE INFO THEY'LL FIND IN PS SO THEY CAN AVOID MY FATE.



XM1216 SUGV Battery

The BB-2590/U, NSN 6140-01-490-4316, is the **only** approved battery for the XM1216 small unmanned ground vehicle (SUGV) system. Using any other battery in the chassis or operator control unit (OCU) could cause damage or failure of the robot and OCU.

STE-M1/FVS Continuity Test Probe

The STE-M1/FVS test set's continuity test probe assembly, NSN 6525-01-102-6878, shown as Fig F6 in TM 9-4910-751-14&P (May 91 w/Ch 2, Mar 97), is no longer available. But you can still put the probe assembly together by ordering its down parts from the same Fig. Note that Items 4 and 11 have been replaced by NSNs 5999-01-098-8726 and 6625-00-975-3998 respectively.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?