


WHOSE JOB IS IT?

WHADAYA MEAN I DON'T INSTALL THE TRANSMISSION'S INTERNAL FILTER?

IT COMES WITH THE ANNUAL SERVICE KIT!

THAT'S RIGHT!

BUT IT SHOULD ONLY BE REPLACED BY SUSTAINMENT MAINTENANCE!



Word from the field is that units are removing the transmission pan to replace the internal filter on M1117 ASVs and M1200 Armored Knights.


That's understandable since the internal filter is included in the annual service kit, NSN 4910-01-526-7869.

Problem is, replacing the filter is not a field-level task. That's why you don't see a work package for replacing the filter in any of the TM 9-2320-307-23 manuals.

Mechanics that remove the transmission pan to do the work are damaging the transmission. That's why the filter replacement should **only** be done by sustainment maintenance.

Paperwork is underway to get the internal filter removed from the annual service kit. But until then, **don't** try to install it.

Transmission's internal filter should only be replaced by sustainment maintenance



Mechanics are not authorized to remove transmission pan