


WHERE'S THE TOOL?



SAYS HERE YOU'RE SUPPOSED TO HAVE A BARREL SUPPORT REMOVAL TOOL!

Dear Half-Mast,

The M2A1 machine gun's TM 9-1005-347-23&P lists a barrel support removal tool in WP 0026 under the removal and installation instructions. But we can't find an NSN for the tool. Is there one?


SGT B.B.

Dear Sergeant,

There is no NSN because there is no tool. The tool was included in the TM by mistake. All references to the tool will be removed in the next revision to the TM.


Half-Mast

Check for Loose M240L Pistol Grip



Look in pistol grip for loose or missing bolt

WHEN OPERATORS AND SMALL ARMS REPAIRMEN DO THE PMCS FOR THE M240L MACHINE GUN, THEY ALSO NEED TO CHECK FOR A LOOSE PISTOL GRIP.



Look inside the pistol grip and make sure the bolt and washer are securely installed. If the bolt is loose or missing, the M240L is NMC.

This check will be added to the PMCS for both TM 9-1005-313-10 and -23&P.

Remember, the M240B and M240L trigger assemblies are not interchangeable. Use the correct trigger.