

Turn in M203s As Is

SINCE YOU'RE GETTING M320s, IT'S TIME FOR ME TO HIT THE ROAD. YOU GONNA FIX ME UP FIRST?

NO, WE CAN TURN YOU IN AS IS.



When your unit receives the new M320/A1 grenade launchers, it's time to turn in your old M203 grenade launchers. But don't waste time bringing your M203s up to 10/20 standards. That's not necessary.

Turn in your M203s as is and coded **F**. Make sure they are packed well so they won't be damaged during shipment. Include all documentation and serial numbers so that Anniston Army Depot can easily process them.

Send them to:

(DODAAC) SV3120
DLA Disposition Anniston
7 Frankford Ave
Bldg 360 ATTN: Justin Houston
Anniston, AL 36201


Put on the package:
"POC: Justin Houston,
justin.houston@dla.mil
(256) 741-5343"

If you have questions about M203 turn-in, contact TACOM's Veronica Cook at DSN 786-1268, (586) 282-1268, or email: veronica.l.cook4.civ@mail.mil

If you have technical questions about the M203, contact TACOM's Matt Williams at DSN 786-1331, (586) 282-1331, or email: matthew.w.williams21.civ@mail.mil

Extract Bad M249 Extractor Kits

Some of the springs in the M249 machine gun's extractor kit, NSN 1005-01-383-0168, have been reported as out of tolerance. The bad springs make it difficult to fit the helical compression spring over the extractor's straight headless pin. That can lead to extraction failures.



Check for extractor kits from CAGE 06MA8 dated prior to 2014. If you find any, replace them by contacting TACOM's Anna Kersey at DSN 786-1337, (586) 282-1337, or email: anna.l.kersey.civ@mail.mil

For any other M249 problems, contact TACOM's Andre Pilgrim at DSN 786-1335, (586) 282-1335, or email: andre.v.pilgrim.civ@mail.mil