

HYEX...

Fuel Filter Service Interval Updated

HEY, I'VE HIT 240 HOURS OF OPERATION. IT'S TIME TO REPLACE MY LUBRICITY FUEL FILTER!

BUT YOUR TM SAYS TO REPLACE IT EVERY 500 HOURS.


HMMM...MAYBE I SHOULD CHECK WITH HALF-MAST.

Dear Half-Mast,

I need a little help with the lubricity filter, NSN 2940-01-567-4018, that's used on the HYEX Model 240D LCR excavator.

According to Item 9 in the Machine PMCS on WP 0310-6 of TM 5-3805-294-23-2 (May 12), the filter is supposed to be replaced after every 500 hours of operation. But when a new filter comes in, it's labeled, "CAUTION: TO BE SERVICED EVERY 250 HOURS."

New filter says to replace every 250 hours



MADE IN U.S.A

CAUTION: TO BE SERVICED EVERY 250 HOURS

So is TM 5-3805-294-23-2 wrong in requiring a 500-hour interval or is there a different, 500-hour filter we should be using?

Mr. J.R.

GOOD CATCH! THE REPLACEMENT INTERVAL FOR THE HYEX'S LUBRICITY FILTER IS 250 HOURS.

TM 5-3805-294-23-2 WILL BE UPDATED TO SHOW THAT AT THE NEXT CHANGE.