



TAKE BITE OUT OF SWITCH GUARD



Crewmen, it's easy to bump into your Stryker's switch guard, NSN 5930-20-000-9243, as you're entering or exiting the vehicle. Your personal gear and weapon can also take a toll on the switch guard's rubber seal, damaging it or knocking it off completely.

The entire switch guard has to be replaced if the seal is damaged or missing. That'll cost your unit about \$100. And if the rubber seal on the guard goes missing, the exposed metal edge can take a bite out of you.

You can save some money and maybe some skin by removing the seal, applying a little adhesive to the metal guard and reinstalling the seal. That'll help keep the seal in place. NSN 8040-00-995-7080 brings a 24-oz can of spray adhesive that's made for bonding pads and trim to metal.



Apply adhesive under switch guard's rubber seal to keep it in place