


HANDLE WITH CARE

THANKS TO YOUR
ROUGH TREATMENT, I
HAVE TO GO ALL THE
WAY TO THE DEPOT
TO BE **FIXED!**

ALL YOU
HAD TO
DO WAS
BE **GENTLE**
WITH ME!




Too many AN/PED-1, -1A and -1B lightweight laser designator rangefinders (LLDR) are taking long trips to the depot for repair because Soldiers forget they need to be handled with care.

The most common reason for LLDR damage is they're dropped on their side. Even if an LLDR is in its soft case, the impact can crack it. Always lay an LLDR down gently.

LLDRs are also damaged when Soldiers aren't careful loading or unloading them from vehicles. Never toss an LLDR in a truck or let it bang against anything when you take it out of a vehicle. Never let an LLDR roll around in a vehicle during travel, either. Secure it before you hit the road.

Rough handling damages LLDR!



To help Soldiers remember to treat their LLDRs with care, stencil **HANDLE WITH CARE** on the cases.

For info on taking care of your LLDR, see TM 11-5955-315-13&P.

If your LLDR or any target locator module (TLM) or laser designator module (LDM) needs repair, contact CECOM's Richard Gendreau at (443) 395-1366 or email: richard.j.gendreau.civ@mail.mil

Questions about your LLDR? Contact PEO Soldier's Mary Ellen Robel at (703) 704-1541 or email:

maryellen.j.robel.civ@mail.mil