



AVOID A COVER CALAMITY



Crewmen, be **very** careful when opening and securing the transmission oil filler access cover on your M88A1.

Because the boom is often in the way, the latch that holds the cover up may not catch properly. The cover is very heavy, so you don't want to be in the way if it falls suddenly.



Some mechanics have had their fingers broken when an unsecured cover came crashing down.

So, when raising the cover, make sure the latch catches properly. If it won't because of the boom, either raise the boom slightly, or get someone to hold the cover up.