WATCH THOSE FINGERS!



CUT, BRUISED OR SPRAINED FINGERS SEEM TO GO HAND-IN-HAND WITH SOLDIERS ASSIGNED TO UNITS WITH ARMORED SECURITY VEHICLES (ASVS).

ACCORDING TO ACCIDENT REPORTS, THE CULPRIT IS...

...THE UPPER DOOR ON THE **BACK** OF THE VEHICLE.

IF YOU'RE NOT CAREFUL, MY DOOR IS GONNA GETCHA!

THIS DOOR IS VERY HEAVY AND CAN CATCH A DRIVER OR CREWMAN BY **SURPRISE!**